

600 GELCOAT CUT COMPOUND

Using 600, for the painted surfaces of yachts, fiberglass molds, surfboards, or gelcoat etc., can remove the marks of P1200. If want to achieve a higher brightness and remove the swirl marks and hologram, could use 1600, 2600 or 3600 to obtain a higher brightness surface.

