

# Ningxia Baishi Hengxing Food Technology Co.,Ltd

Xinshui Agricultural Product Industrial Park, Zhongning, Ningxia, China

## Process Flow Chart for Goji Berry

①Raw material resources ( According to normalized standard of Goji berry planting in own base → Picking→ Sun-curing ) → ②Raw material acceptance **【Key control points】** → ③Drying → ④Grade Sorting → ⑤Color selection → ⑥Manual picking(1st time) → ⑦Winnowing removing impurity→ ⑧De-stonner remove stone → ⑨Electrostatic hair separation → ⑩Manual picking (2nd time, via artificial picking platform → ⑪Metal detecting → ⑫Ultraviolet sterilization → ⑬Full automatic packaging(inner package) → ⑭Outer packing workshop (outer package ) → ⑮Inspection(proportionate sampling ) → ⑯Warehousing → ⑰Labeling → ⑱To be sold after inspection approved(Secondary sampling inspection)