




# DWB

## Aluminum Weighing Indicator



### Function

**Keys:** Power On/Off, Accumulate, Zero, Tare

**Functions:** Weighing, counting, RTC function (optional), weighing units, power-on zero tracking, auto power-off mode, digital noise filter, full tare capacity, programmable capacity and division, low battery icon

**Structure:** Industrial aluminum housing, powered by AAA batteries

**Applications:** Various occasions with external weighing sensors (e.g. platform scales, floor scales, etc.)

### Specifications

Accuracy	30000
Weighing Units	g, kg, lb, oz
Product Dimensions	170mm x 27mm x 95mm
Net Weight	0.45 kg
Class	III
Display	LCD display (116*38mm)
Power Supply	DC (9-12V/1A), 4×AAA batteries
Temperature	-10°C to 40°C (14°F to 104°F)
Interface	RS232/USB

