

Apply to all departments



Zhejiang Haichuang Medical Devices Co., Ltd. ADD: F1, Building 3, No. 146, E Chaofeng Rd, Linping, Yuhang Economic Development, Hangzhou, Zhejiang, China

Drainage tube fixing device does not cause secondary damage to the skin, while increasing the efficiency of the doctor. It is completely change the traditional fixing treatment that reduce the risk of tube displacement and accidental fall off.



Traditional stitching fixing Treatment

Product Features:

Treatments Projects	Traditional stitching fixing	Drainage tube fixing device
Skin damage	Yes	No
Tube adjustment	No	Yes
Risk of fall off	Yes	No
Cleaning	Difficult	Convenient
Allergies	Yes	Low
Risk of infection	High	No
Appearance	Messy	Tidy
Comfort	Low	High

Product Features:

- "Non-invasive" and "Rotating design", avoid secondary damage and much improve the operating time and stability;
- Extremely low allergenic materials, to prevent rash, blisters and other allergies;
- Visualized design for easy cleaning and observation;
- Increase the maintenance period and patient's comfort;
- Disposable product to reduce potential complications;
- Can be used for all different sizes of drainage tubes and catheters;

Clinical Trial Case Picture:









